

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3290386	motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:42
L2	5018	1 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:46
L3	484435	1 and (electric ) near3 (motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:43
L4	1305	2 and (electric ) near3 (motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:46
L5	362	4 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:43
L6	271	5 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:43
L7	61	6 and (electric ) near3 (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:43

## EAST Search History

L8	4152	(strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing casing frame ).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:50
L9	340	8 and (electric ) near3 (motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:46
L10	103	8 and (electric ) near3 (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:48
L11	465	8 and (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:48
L12	47	8 and (motor).ti.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:48
L13	245	8 and (motor).ab.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:48
L14	57	13 and (flange )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:50

## EAST Search History

L15	41	"5015926"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:51
L16	362	5 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:50
L17	0	15 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:51
L18	18	15 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:51
L19	214	318/9.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:51
L20	24	19 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:57
L21	5	20 and (housing)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:03

## EAST Search History

L22	19	("3609498"   "3736486"   "4190792"   "4207507"   "4289996").PN. OR ("4482847").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/10/12 21:56
L23	3	22 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell )	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:03
L24	1	23 and (housing)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:58
L25	65837	(drive) near3 (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:58
L26	3592	25 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:59
L27	733	26 and (housing).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:58
L28	77	25 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 21:59

## EAST Search History

L29	24762	rotary near3 actuator	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:03
L30	3683	rotary near3 actuator.clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:03
L31	1133	30 and (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:03
L32	85	31 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L33	34	32 and (housing).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L34	204175	power near3 transmission	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L35	3572	34 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:13

## EAST Search History

L36	493	35 and (housing).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L37	149	36 and (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:13
L38	49	37 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L39	31	38 and (shaft).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:11
L40	55	34 and (strain stress load force pressure) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell ) near3 (housing).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:13
L41	7	40 and (motor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/12 22:13